

Cryomagnets Interconnections

Status of the helium guard repair Interconnection cryostats **Geometrical displacement Status** Was also presented at ICC 15/02/2008 Update on sector 4-5 consolidation Quick interconnection overview **Open points**

MARIC 20/02/2008



Helium guards repair status

Sector	To be replaced	Done	<u>Remark</u>
1-2	24	12	Completed
2-3	9	8	Completed
3-4	3	3	Completed
<mark>4-5</mark>	8 ?	0	During shutdown of 4-5
<mark>5-6</mark>	13 ?	0	After warm-up
6-7	25	25	Completed
7-8	7	7	Completed
8-1	1	1	Completed

* Components for second part of sector 4-5 and 5-6 are ordered ; delivery has been postponed to W9 ; still OK with the schedule but to watch

- * Endoscope inspections done in all sectors but 4-5 and 5-6
- * Under control




<u> Tolerances :</u>

From LHC-LE-ES-0001 rev 3.2

"Centreline of cold bore inner surface has to be kept all over its length inside a cylinder of radius 1.6 mm aligned on the beam theoretical position for aperture reasons."


Interconnection Cryostats Update wrt ICC 15/02/2008 : Geometry problem

But more critical on Q11 side ; relaxed by about 1 mm at the other extremity (B Jeanneret)





Welds to re-close the shuffling module





Welds to re-close the vacuum vessel




MARIC 20/02/2008



Sequence of events :

1. Measurement of fiducials of CC L8 before intervention

2.Measurement of displacement in SM18 on a test cryostat after reclosure of a vacuum vessel (Displacement of about 1.5 mm)



3. Measurements taken with Romer Arm (TS-MME) in 7-8 to have references : -Displacement of SM wrt cryostat for SM welds,

-Measurement of extremities of CC wrt neigbours ; done for R7 and L8

Trials to compensate by welds on the other side but limited effect (0.3 mm)



Sequence of events :

4. Last Friday (15/2), measurements of extremities of CC L8 and R7 were taken and under analysis ; it was decided to close to be able to perform leak test and, in case position is acceptable, go on with the programme for restart of cooldown

5.Monday 18/2 : Meeting with TS-SU, TS-MME, AB, MCS to review the results of Romer arm and Leica measurements wrt the acceptable tolerances

-Some displacement wrt neighbours (Q11R7) of 1.2 mm ; not within the specification

- -Reference measurement at L8 was lost
- -Blind for the central part
- -Define a sequence to take reference measurement for the next sectors (6-7 and on...)
- -Define a sequence if it is possible to intervene in 7-8

6. Tuesday 19/2 :

-Leak tests (air to insulation vacuum and CM to insulation vacuum with 1.1 bar) were performed, in advance by one day on schedule as residual was good

-R7 : Leak tight / L8 : Leak on the closure of the cryostat (air to insulation vacuum 10⁻³ mb l/sec) -A very aggressive schedule was done to carry out the intervention in 7-8 with no or very limited impact on the schedule (Thanks to TS, HCC, VAC, CRG, MEI, MCS, IEG ... colleagues for availability, flexibility, information, adaptability)

MARIC 20/02/2008



Solution in 7-8 :

- 1. Reopen interconnections to allow access to CM extremities (IEG) [Done]
- 2. Perform a new complete in-situ fiducialisation of extremities wrt fiducials (TS-SU)
- [Done for R7 ; today for L8] Already done for some dipoles when fidu was lost for corrosion
- 3. Realign the CC to its nominal position (TS-SU) [Done for R7 ; today for L8]
- 4. Check position of extremities wrt neighbours with Romer arm (TS-MME) [Today/Tomorrow morning]
- 5. Reclose the ICs [tomorrow]
- 6. Fill CM with 6 bars
- 7. ELQA on Friday morning
- 8. Leak test to be repeated

MARIC 20/02/2008



Solution in other sectors

- 1. Open interconnections to allow access to CM extremities (IEG)
- 2. Access the central foot to perform ref measurement (MCS)
- 3. Perform a reference measurement of fiducials (TS-SU)
- 4. Perform measurement of CM extremities wrt neighbours and also of the central foot wrt to ground (TS-MME)
- 5. After rewelding, Perform a new fidu and realign the CC to its nominal position (TS-SU)
- 6.Check position wrt neighbours and ground for the central foot (TS-MME)
- If too high deformation of the CM, use the central post to correct the shape (If required only) 7. Reclose the ICs



A further detailed presentation of the method and results obtained for the nominal procedure and for the rescue one (7-8) will be done by TS-SU to determine the accuracy

MARIC 20/02/2008



Interconnection Cryostats

Sector	Repair of ICCs	Completion date
1-2	Planned (4th)	End W11
	Planned (5th)	W12
3-4	Planned (6th)	W13
4-5	Planned (7th) During consolidation	W17
5-6	Afer warm-up (8th) - 3 units ?	?
	Insulation reinforcement / Ref measurements	Beginning W9 (delay)
	Repositionning	End W8
8-1	Under opening	Mid W10

Delay in 6-7 : due to setting-up of measurement procedures in parallel with 7-8 and fire brigade exercise tomorrow



Sector 4-5 consolidation (update)

Starting date : 17/03/2008 (Monday W12)


Sector 4-5 Consolidation

1	Plug-in modules	7 weeks
2	Photometer test	3 days
3	Y lines	3 weeks
4	Helium guards	2 weeks
5	Leaks	3 weeks ?
6	Triplet 5L	8 weeks
		2 weeks ?
8	Connection Cryostats	5 weeks
9	CC splices	1 day
10	DFBs cables	?




Cryomagnets interconnection

Line Y interruptions : Analysis to localise the defect (C Maglioni, V Parma)



Q18-Q19 L5 cooled by conduction



Analysis allows to determine to 1/2 ICs where the disruption is.

The approach for repair and inspection is defined



Cryomagnets interconnection

Intervention on DFB cables ? (M Felip, A Perin)




DFBA	Position		
DFBAH	4R		
DFBAI	5L		
DFBAO	8L		
DFBAA	1L		
DFBAP	8R		
DFBL	Position		
DFBL	Position		
DFBL DFBLD	Position 5L		

1.Decision on necessity to repair ? To be taken in the coming days

2.For DFBAs, both extremities are accessible ; can be managed (MCS, TS-MME) ; can be in the shadow of triplet reconnection

3.For DFBL: Availability of water cooled cables can prevent us from doing the intervention

4.For DFBM (8L&2L), WCC ?



CERN	Quick IC overview	1-2 2-3 QOQL7 R 2R QQQE7 R QQQE8.48 R QQQE8.48 R QQQE8.48 R QQQE8.48 R QQQE8.48 R QQQE8.48 R QQQE8.48 R QQQE8.49 R 2658.9 R	3-4 4-5 5-6 6-7 7-8 8-1 38 48 58 68 78 88	1-2 2-3 3-4 4-5 5-6 6-7 7-1 22 3L 4L 3L 6L 7L 3L Q351:534 L Q351:533 L Q351:535 L Q351:555 L Q351:5555 L Q351:5555 L	8 8-1
<u>Sector</u>	<u>On-going</u>		Planned		
1-2	2 IC opened ; Jack problem (Status)		Leak test, closure	of Ics, Repair of ICCs	
2-3	1 IC opened for leak repair QBQI.23L3.(nc	892781)	Leak repair (W9) /	Repair of ICCs	
3-4	NA		ELQA - Purge and flushing, Repair of ICCs		
4-5	Q1/Q2/Q3 IC / Warm-up		Consolidation from	n W12	
5-6	Cold		Cooldown		
6-7	Repair of ICCs		Cooldown		
	Repair of ICCs up to end of W8		Restart cool down		
8-1	Cold stand-by / Repair of ICCs	Permise according to the	Restart cool down		
<u>19 ICs to close:</u> 15 in the arc 12 for CC, 1 for LT, 2 for jack 4 in L5 triplet		* Repair * Inspec * Not (ye	<u>in 1-2 ?</u> ? : Meeting on site to tion launched by TS- t) critical tion by surveyors of		
- Q1/0	Q2 closed Q3 under closure	QBQ123 R QQB123 R QBB1: A04 R QBB2: A04 R QBB2: A04 R QBB2: A03 R		QBB_A19_L	
Aller		QBE 527 R QBC1 27 R QCB1 28 R QBE 528 R QBE 28 R QBE 28 R QBE 28 R QBE 29 R QBE 20 R QBE 20 R QBE 31 R QBE 32 R QBE 32 R QBE 32 R QBE 33 R QBE 32 R </td <td></td> <td>QSB: B15 L QSB: A15 L QSB: A15 L QSB: A15 L QSB: B14 L QSB: B14 L QSB: B14 L QSB: B14 L QSB: B14 L QSB: B14 L QSB: B13 L QSB: B13 L QSB: B13 L QSB: B13 L QSB: B12 L QSB: B12 L QSB: B10 L QSB: B12 L <t< td=""><td></td></t<></td>		QSB: B15 L QSB: A15 L QSB: A15 L QSB: A15 L QSB: B14 L QSB: B14 L QSB: B14 L QSB: B14 L QSB: B14 L QSB: B14 L QSB: B13 L QSB: B13 L QSB: B13 L QSB: B13 L QSB: B12 L QSB: B12 L QSB: B10 L QSB: B12 L <t< td=""><td></td></t<>	
Sector and a sector		QBBLA34 R QBBLB34 R QBQL34 R		G8G.8 L GG9.7 L	