


MASTER INTERCONNECTION FLOW DIAGRAM

for ARC (Q11R to Q11L) sectors from 3-4 Q25L4 till 7-8 Q25L8 via 4-5, 5-6, 6-7



L E G E N D	QBQI WITH JUMPER	FREE OPERATION FOR WORK	COORDINATION	INFORMATION FROM OUTSIDE FW CHART AREA TESTS REQUIRING PIECE OF EQ. OUT OF FW CHART ICIT INSPECTION ON V,E,X,C' WELDS. NECESSARY FOR VAC TEST CERN QA IC CERTIFICATION BEFORE CLOSURE	JUMPER REGION WELD LD2 PRESENT IN JUMPERS 11 15 19 23 27 31
	QBQI WITHOUT JUMPER	OPERATION NEEDING GREEN LIGHT FROM COORD	VAC TEST		
	QBQI	OPERATION NEEDING THE EXECUTION OF A PREVIOUS OPERATION	ELECTRICAL TEST		
	QBBI		LONG ELECTRICAL TEST (MAPQ, MHAVQN)		
	QBBI WITH JUMPER		RECALL TO OUTPUT IN OTHER POINT OF WF CHART		